

GSR Calibration Adaptor

Instructions for Use

1. Connect Snap ends from the 76740ADP to the 76740LX Polygraph Calibrator
2. Connect GSR Finger Electrode cables to DAS
3. Insert GSR Finger Electrodes into slots in 76740ADP
4. Follow directions on 76740LX Polygraph Calibrator to test GSR Finger Electrodes





3700 Sagamore Parkway North

Lafayette, IN 47904 USA

Tel: (765) 423-1505 • (800) 428-7545

Fax: (765) 423-4111

info@lafayetteinstrument.com

www.lafayetteinstrument.com